

AD-A063 123

6AI CONSULTANTS INC MONROEVILLE PA

F/6 13/2

NATIONAL DAM INSPECTION PROGRAM. KEYSTONE STATIONS DAM NDI NUMB--ETC(U)

JUN 78 B M MIHALCIN

DACW31-78-C-0052


NL

UNCLASSIFIED

1 OF 1
AD
A063123



END
DATE
FILMED
3-79
DDC



MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

KEYSTONE STATION DAM

NDI Pa - 275 .

Number

Ohio River Basin, Plum Creek, Armstrong
County, Pennsylvania.

LEVEL

PHASE I REPORT
National Dam Inspection Program

①

Keystone Station Dam

Pennsylvania

Armstrong County

Plum Creek

15 May 1978

Inspection Team - GAI Consultants, Inc.
570 Beatty Road
Monroeville, Pennsylvania 15146

Based on a visual inspection, past performance, and available engineering data, the dam is considered to be in excellent condition. The spillway and pre-split rock channel are capable of passing the flow resulting from a storm of the PMF intensity without overtopping.

It is recommended that a formal warning system be developed to insure the safe evacuation of all downstream inhabitants in the event of an inordinately heavy rainfall.

In addition, it is recommended that qualified personnel continue to inspect the facility on a periodic basis to insure that hazardous conditions do not develop.

ACCESSION for	
RTIS	White Section <input checked="" type="checkbox"/>
DDC	Buff Section <input type="checkbox"/>
UNANNOUNCED	<input type="checkbox"/>
JUSTIFICATION	
Per DDC Form	
BY on file	
DISTRIBUTION/AVAILABILITY CODES	
Dist.	AVAIL. and/or SPECIAL

DDC
RECEIVED
JAN 11 1979
D

Contract DACW31-78-C-0052

i

DISTRIBUTION STATEMENT A
Approved for public release;
Distribution Unlimited

Approved:

G. K. Withers
G. K. WITHERS
Colonel, Corps of Engineers
District Engineer



Date July 7, 1978

Date 20 11 78



Overview Photograph of Keystone Station Dam Taken from the Right Abutment.

TABLE OF CONTENTS

	<u>Page</u>
SYNOPSIS	i
OVERVIEW PHOTOGRAPH.	iii
TABLE OF CONTENTS.	iv
SECTION 1 - GENERAL INFORMATION.	1
1.0 Authority.	1
1.1 Purpose.	1
1.2 Description of Project	1
1.3 Pertinent Data	2
SECTION 2 - ENGINEERING DATA	5
2.1 Design	5
2.2 Construction Records	6
2.3 Operation.	6
2.4 Other Investigations	6
2.5 Evaluation	6
SECTION 3 - VISUAL INSPECTION.	7
3.1 Observations	7
3.2 Evaluation	8
SECTION 4 - OPERATIONAL PROCEDURES	9
4.1 Normal Operating Procedure	9
4.2 Maintenance of Dam	9
4.3 Maintenance of Operating Facilities.	9
4.4 Warning Systems in Effect.	9
4.5 Evaluation	10
SECTION 5 - HYDROLOGIC/HYDRAULIC EVALUATION.	11
5.1 Design Data.	11
5.2 Experience Data.	11
5.3 Visual Observations.	11
5.4 Overtopping Potential.	11
5.5 Spillway Adequacy.	12
SECTION 6 - EVALUATION OF STRUCTURAL INTEGRITY	13
6.1 Visual Observations.	13
6.2 Design and Construction Techniques	13
6.3 Past Performance	13
6.4 Seismic Stability.	13
SECTION 7 - ASSESSMENT AND RECOMMENDATIONS FOR REMEDIAL MEASURES.	14
7.1 Dam Assessment	14
7.2 Recommendations/Remedial Measures.	14

TABLE OF CONTENTS

APPENDIX A - CHECK LIST - ENGINEERING DATA	1
APPENDIX B - CHECK LIST - VISUAL INSPECTION	2
APPENDIX C - HYDROLOGY AND HYDRAULICS	3
APPENDIX D - PHOTOGRAPHS	4
APPENDIX E - GEOLOGY	5
APPENDIX F - FIGURES	6
APPENDIX G - REGIONAL VICINITY MAP	7

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM
KEYSTONE STATION DAM
ID# NDI PA-275; PENNDER# 3-28

ABSTRACT

1.0 Authority.

The Dam Inspection Act, Public Law 92-367 authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of inspection of dams throughout the United States.

1.1 Purpose.

The purpose is to determine if the dam constitutes a hazard to human life or property.

1.2 Description of Project.

ABSTRACT

a. Dam and Appurtenances. Keystone Station Dam is a rolled earthfill structure approximately 1,200 feet long and 100 feet high at the original streambed. A pre-spilt rock channel spillway with a concrete overflow crest and concrete control weir is located along the southeast shore approximately one mile upstream of the dam. The outlet works serving the facility consists of a 24-inch cast iron pipe which discharges into a 7-foot by 7-foot concrete box culvert. The outlet controls are housed at the reservoir tower located upstream behind the left abutment and are accessible by a foot bridge. The dam is equipped with several other features such as piezometers, relief wells at the toe, and weirs to measure surface runoff, seepage, and normal discharge.

b. Location. The dam is located along the north branch of Plum Creek in Armstrong County, Pennsylvania. The town of Elderton is located approximately 4 miles to the southwest along U. S. Route 422. The dam and its watershed are shown on the following U.S.G.S. 7.5 minute quadrangle sheets; Elderton, Rural Valley, and Plumville, Pennsylvania. The coordinates of the dam are N79° 18' 02" and W40° 43' 38".

c. Size Classification. Large (100 feet high, 27,000 acre-feet).

d. Hazard Classification. High (possible loss of life greater than three - see Section 3.1c).

e. Ownership. Keystone Station (operated by Pennsylvania Electric Company, Penelec).

Joint Ownership by:

- a) Atlantic City Electric Company
- b) Baltimore Gas and Electric Company
- c) Delaware Power and Light Company
- d) Jersey Central Power and Light Company
- e) Pennsylvania Power and Light Company
- f) Philadelphia Electric Company
- g) Public Service Electric and Gas Company

f. Purpose of Dam. The purpose of the dam and reservoir is to provide the water requirements of nearby Keystone Station Generating Plant.

g. Design and Construction History. The dam was designed by Gilbert Associates, Inc., Reading, Pennsylvania. Construction began in early 1965 and had been substantially complete by November of that same year. No major modifications appear to have made since construction.

1.3 Pertinent Data.

a. Drainage Area. 20.6 square miles.

b. Discharge at Dam Site.

Maximum Known Flood at Dam Site - Data not available.

Outlet works conduit at operating pool elevation - discharge curve not available. Maximum discharge at normal pool (elevation 1077) calculated to be approximately 180 cfs.

Ungated Spillway Capacity - 32,229 cfs.

Total Spillway Capacity - 32,229 cfs.

c. Elevation (feet above mean sea level).

Top of Dam - 1093.

Maximum Pool Design Surcharge - 1090.

Maximum Pool of Record - Not known.

Normal Pool - 1077.

Upstream Portal Invert Outlet Conduit - 1015.

Downstream Portal Invert Outlet Conduit - 993.5.

Streambed at Centerline of Dam - 993.

Maximum Tailwater - Not known.

d. Reservoir.

Length of Maximum Pool - 5.0 miles-estimate.

Length of Normal Pool - 4.9 miles-estimate.

e. Storage (acre-feet).

Spillway Crest - 27,000.

Design Surcharge - 40,000-estimate.

Top of Dam - 43,150-estimate.

f. Reservoir Surface (acres).

Top of Dam - 1075-estimate.

Maximum Pool - 1050.

Spillway Crest - 825.

g. Dam.

Type - Rolled earthfill.

Length - 1,200 feet.

Height - 99.5 feet maximum.

Top Width - 20 feet.

Side Slopes - Upper Downstream 2.5H:1V
Lower Downstream 3.5H:1V
Upstream 3.0H:1V

Zoning - Homogeneous earth with a downstream drainage blanket. Three feet of riprap on upstream face and a dumped riprap downstream toe.

Cutoff - Drawings indicate a cutoff trench excavated to rock and backfilled with embankment material.

Grout Curtain - Beneath centerline of cutoff trench from abutment to abutment. Primary holes 100 feet deep on 20-foot centers, alternate holes 50 feet deep on 20-foot centers.

h. Outlet Conduit.

Type - 7 feet by 7 feet concrete box culvert.

Length \approx 1060 feet.

Closure - Sliding gate at inlet entrance and valved along the 24-inch conduit that feeds the concrete culvert.

Access - Foot bridge to intake tower.

Regulating Facilities - Valves are manually controlled from reservoir tower.

i. Spillway.

Type - Chute spillway pre-split into natural rock.

Weir Length \approx 180 feet.

Channel Length \approx 1700 feet.

Crest Elevation - 1077.

Upstream Channel - Not applicable.

Downstream Channel - Channel cut into natural rock with bed sloping at 0.005.

j. Regulating Outlets. Ungated overflow spillway with crest elevation at 1077. Low flow outlet to outlet conduit with invert elevation 1015 in intake tower.

SECTION 2 ENGINEERING DATA

2.1 Design.

a. Design Data Availability and Sources.

1. Hydrology and Hydraulics. Hydrologic and hydraulic design reports are available from Gilbert Associates, Inc., Reading, Pennsylvania. Some information related to storage capacity, spillway capacities, and rainfall data were available from contract drawings.

2. Embankment. A stability analyses was provided as part of the contract drawings. This data is reproduced in Appendix F as Figure 2.

3. Appurtenant Structures. A complete set of design reports is reportedly available from Gilbert Associates, Inc., Reading, Pennsylvania, however, they were not reviewed in this investigation because of time restraints.

b. Design Features.

1. Embankment. Construction drawings, photographs, and reports indicate the embankment was constructed of compacted earth. The material was reportedly compacted to 95 percent of modified proctor on the wet side of optimum moisture. Laboratory test data, compaction results, etc., are available from Penelec and GAI files. The upstream slope is mantled with dumped riprap at an angle of 3H to 1V, whereas the downstream surface is covered with grass with the upper portion sloped at 2.5H to 1V and the lower portion sloped at 3.5H to 1V. The downstream slope also has a rock toe composed of durable sandstone riprap.

2. Appurtenant Structures.

a) Spillway. The spillway is a chute type pre-split channel cut into rock. It is equipped with an ogee-crested weir at the spillway entrance and an ogee-crested weir approximately 600 feet downstream. Calculations indicate the spillway capacity is controlled by the upstream ogee-crested weir and is limited to a maximum discharge of approximately 32,000 cfs.

b) Outlet Works. The facility is equipped with a single outlet which comprises the entire works. It is a 7-foot by 7-foot concrete box culvert fed by a 24-inch cast iron pipe. Plan locations and details are depicted in Figures 3, 4, 5, and 6, and in Photographs 3 and 4. As indicated in the drawings, a series of valves control the flow at the inlet.

c) Specific Design Data and Procedures. No design reports pertinent to the outlet facilities were available.

2.2 Construction Records.

Ebasco Services, Inc., served as general contractor at this project and compiled a series of construction reports which are available on Micro-Fiche from PennDER and Penelec files. Furthermore, a complete pictorial construction history was compiled by the firm E. D'Appolonia Associates and is available from the files at GAI Consultants.

2.3 Operating Records.

Compiled daily and maintained at the Keystone Electric Generating Station.

2.4 Other Investigations.

Continuous monitoring of the embankment facility is provided by D'Appolonia Consulting Engineers, Inc.

2.5 Evaluation.

The available data is considered sufficient for a Phase I evaluation as presented in this report.

SECTION 3
VISUAL INSPECTION

3.1 Observations.

a. General. The general appearance of the structure and its appurtenances suggests that the facility is well maintained and is in excellent condition.

b. Embankment. The upstream slope of the dam is mantled with durable riprap which was apparently dumped in place. The downstream portion of the embankment is covered with vetch and other grasses, and is provided with a 10-foot wide berm on which an asphalt gutter has been constructed. This gutter contains three catch basins that divert surface runoff into 8-inch concrete pipes which discharge into the rock toe at the base of the slope. Minor seepage and sloughing was noted on the right abutment near the elevation of the berm.

The dam is also provided with a series of piezometers and a system of relief wells located at the downstream toe (see Figure 3 and Photographs 6 and 7). The relief wells were not discharging at the time of inspection; however, one of the piezometers (located in the center of the dam at the toe) was discharging water and gas bubbles suggesting that the piezometer had intersected an old gas well. (Construction photographs indicated a well was located near the toe of the dam.) The piezometers are reportedly monitored on a monthly basis and the results are computed and plotted by a consulting engineer for Penelec. A discussion with the consultant indicated that the readings are within tolerable levels and no further investigations or remedial work is being contemplated.

c. Appurtenant Structures.

1. Spillway. The spillway, spillway abutments, and pre-split rock channel walls all appeared to be in excellent condition (see Appendix E). It was reported that some additional rock bolts had been installed in the spillway channel walls and that gunnite had been applied in areas following the "Agnes" storm in 1972.

2. Gate House Valves. The gate house and valves which control the release of water into the downstream channel via a 7-foot square concrete box culvert appeared to be in satisfactory condition. According to a representative of the power company, the gate controls are maintained on an as-needed basis.

3. Reservoir Area. The slopes adjoining the reservoir are moderate to steep and are more or less equally divided between agricultural and wooded areas. No signs of slope distress were observed with the exception of some minor soil sloughing around the perimeter of the reservoir.

4. Downstream Channel. The area downstream of the Keystone Station Dam can be characterized as a sparsely wooded, broad (1500 feet wide), gently sloping floodplain containing Plum and Crooked Creeks. Numerous improvements are located in the valley within 6 miles of the dam. They include the Keystone Station Generating Plant (approximately 6 miles downstream) as well as many homes in the community of Gastown (\approx 1.5 miles downstream). The total number of dwellings which could conceivably be effected by a breach of the Keystone Station embankment is estimated to exceed 30. Many more improvements, however, could be effected depending on the magnitude of the breach.

3.2 Evaluation.

Since the potential loss of life resulting from a failure of embankment is considerable, the facility is considered to be in a high hazard category.

Since the vegetative covering on the downstream slope was not excessive, it did not preclude an accurate assessment of the conditions.

SECTION 4 OPERATIONAL PROCEDURES

4.1 Normal Operational Procedure.

According to power company personnel, there are no established operational procedures at the facility. The reservoir is maintained at elevation 1077 leaving 16 feet of freeboard to the top of the dam. Excess inflow passes over the spillway and discharges into Miller Run. Miller Run then empties into Plum Creek approximately 1 mile downstream of the spillway. During the "Agnes" storm of 1972, the Miller Run channel downstream of the spillway was scoured due to the excessive outflow at the facility. Reportedly, dredging operations were carried out downstream following the storm.

The only other outlet serving the Keystone Station Dam Facility consists of a 7-foot square concrete box culvert that discharges into the Plum Creek channel (and eventually into Crooked Creek) at the toe of the dam (see Photograph 4). Flow through this outlet is regulated at the gate house to provide recharge into the stream downstream of the embankment.

Water is not transmitted directly to the generating facility via a conventional pipeline, etc. Rather, it is taken directly from Crooked Creek at the plant location.

4.2 Maintenance of the Dam.

Maintenance at the facility is reportedly provided on an as-needed basis by power company personnel.

4.3 Maintenance of Operating Facilities.

Reportedly the dam is visited daily to gauge the amount of flow being discharged into the downstream drainage system. The gate house is equipped with a pressure transducer which along with a V-notch weir, located downstream, affords the opportunity to keep a continuous record of the flow being released to the downstream. The valves appeared to be in good order, however, the valves and sluice gates were not operated in our presence.

4.4 Warning Systems in Effect.

There are no formal warning systems at the facility.

4.5 Evaluation.

The operational procedures currently in practice are considered satisfactory.

SECTION 5 HYDROLOGIC/HYDRAULIC EVALUATION

5.1 Design Data.

Hydrologic or hydraulic design calculations are available from Gilbert Associates, Inc., and Penelec files.

5.2 Experience Data.

Two sets of PMF parameters were available for this analysis and both are used in the calculations. The first was determined from empirical curves supplied by the Baltimore District, Corps of Engineers, for the Ohio River Basin. Based on these curves and a drainage area of 20.6 square miles, the Peak PMF $Q/A = 1,200$ cfs/ sq. mi., Peak $Q = 24,720$ cfs, and flood duration $T = 58$ hours. The second was taken from a graph supplied by Penelec which defines Peak $Q =$ to 33,000 cfs and $T = 33$ hours. The size category is "large" and the hazard rating "high". Therefore, the facility must pass and/or store the PMF.

5.3 Visual Observations.

Dimensions of the embankment were measured in the field and found to agree with available construction drawings. At the time of our field investigation, the channel spillway was in operation and only a visual sight check of dimensions could be made. The outlet works were not fully accessible but are assumed to be functional.

5.4 Overtopping Potential.

As was stated previously in this section, two different PMF Peak Q values were used for this analyses. Both varied considerably with the smaller Peak $Q = 24,720$ cfs having a flood duration of 58 hours while the larger Peak $Q = 33,000$ cfs having a flood duration of 33 hours. The maximum discharge capacity of the spillway was calculated to be approximately equal to 32,229 cfs. This coupled with the maximum discharge of the outlet works of approximately 183 cfs yields a total maximum discharge approximately equal to 32,412 cfs. Thus in the case of the smaller Peak Q the outflow capacity is greater than inflow and consequently such a storm will be passed by the spillway without delay or need for additional storage. However, in the case of the larger Peak Q outflow capacity is slightly less than inflow and it becomes necessary to consider storage capacity in order that excess inflow can be stored until it can be safely discharged. Based on a

normal pool elevation 1077 and the top of design pool elevation 1090, the available design storage is found to equal 13,000 acre-feet. This compares favorably with the volume of storage required of 810 acre-feet calculated for the larger storm relative to discharge capacity. Consequently, it can be concluded the embankment would not be overtopped provided the spillway functions at peak efficiency (see Appendix C).

5.5 Spillway Adequacy.

Based on the analysis in Appendix C the spillway is deemed adequate.

SECTION 6
EVALUATION OF STRUCTURAL INTEGRITY

6.1 Visual Observations.

a. Embankment. Based on visual observations the embankment appeared to be in excellent condition. No evidence of seepage was observed at the time of inspection with the exception of some insignificant sloughing and seepage on the right abutment at the approximate elevation of the berm on the downstream face and some minor flow at the rock toe.

b. Appurtenant Structures. Based on the visual inspection, the spillway structure appeared to be in excellent condition. Some remedial work, including the installation of rock bolts and the application of gunnite was reportedly performed following the "Agnes" storm of 1972.

6.2 Design and Construction Techniques.

a. Embankment. Soil investigation and foundation reports as well as compaction control test results, contract documents, and a photographic record of construction are available from GAI files. This information is also available on micro-fiche in the Penelec files in Johnstown, Pennsylvania.

b. Appurtenant Structures. As mentioned above, a complete record of construction is available from Penelec and GAI Consultants, Inc., files. Based on a cursory review of these data it is thought that the dam and its appurtenances were designed and constructed in a manner consistent with good engineering practice.

6.3 Past Performance.

No records of past performance were available.

6.4 Seismic Stability.

The dam is located within Seismic Zone No. 1 and it is thought that the static stability is sufficient to withstand minor earthquake induced dynamic forces. However, no calculations, investigations, etc., were performed to confirm this conclusion.

SECTION 7
ASSESSMENT AND RECOMMENDATIONS FOR REMEDIAL MEASURES

7.1 Dam Assessment.

a. Safety. The visual inspection, operational history, and available engineering data suggests that the facility is well maintained and in good condition except for some minor seepage and sloughing on the right abutment.

Hydraulic and hydrologic calculations used during our investigation indicated that the spillway is capable of passing and/or storing the flow resulting from a storm of the PMF intensity.

An overall assessment of the project is that it is in excellent condition.

b. Adequacy of Information. The available data was thought to be sufficient to make an accurate assessment of the facility.

c. Urgency. It is suggested that the recommendations listed below be implemented as soon as practical.

d. Necessity for Additional Investigations. No additional investigations are deemed necessary at this time.

7.2 Recommendations.

a. The minor sloughing and seepage on the right abutment near the elevation of the berm and the fact that a piezometer was discharging while the relief wells were not should be noted by the Penelec consultant on future inspections.

b. It is suggested that a warning system be implemented which will provide for the safe evacuation of all downstream residents in the event of an inordinantly heavy rainfall.

c. The owner should continue the periodic inspection of the facility to insure that hazardous conditions do not develop.

APPENDIX A

CHECK LIST - ENGINEERING DATA

CHECK LIST	NAME OF DAM	Keystone Station Dam
ENGINEERING DATA		
DESIGN, CONSTRUCTION, OPERATION	ID #	NDI# PA-275; PENN DER# 3-28
PHASE I		

ITEM	REMARKS	SHEET 1
------	---------	---------

AS-BUILT DRAWINGS

Complete set of contract drawings (except reinforcing and anchor bar lists). As-built drawings available on micro-film. Complete list of contract drawings for entire project.

REGIONAL VICINITY MAP

Drawing 4042 C-426-438.

CONSTRUCTION HISTORY

Reports compiled by Ebasco Services, Inc., on micro-fiche. Pictorial construction history by E. D'Appolonia Associates.

TYPICAL SECTIONS OF DAM

Drawing 4042 C-426-444 "General Plan"
 Drawing 4042 C-426-445 "Cross Sections"

OUTLETS - PLAN

Drawing 4042 C-426-444 "General Plan"

- DETAILS

Drawing 4042 C-426-460 "Piping-Valve Chamber"
 Drawing 4042 C-426-461 "Intake Tower Cross Sections"
 Drawing 4042 C-426-482 "Reservoir Hydraulic Data"

- DISCHARGE RATINGS

RAINFALL/RESERVOIR RECORDS

Available at the Keystone Power Station.

ITEM	REMARKS	ID #	PA-275	SP	T 2
------	---------	------	--------	----	-----

DESIGN REPORTS

Available from Gilbert Associates files.

GEOLOGY REPORTS

None available.

DESIGN COMPUTATIONS

None available.

HYDROLOGY & HYDRAULICS

Drawing 4042 C-426-482

"Reservoir Hydraulic Data"

DAM STABILITY

Drawing 4042 C-426-443

"Stability Analysis"

SEEPAGE STUDIES

None available.

MATERIALS INVESTIGATIONS

2 reports. (GAI files)

BORING RECORDS

1. Subsurface Exploration and Foundation Report, Vol. II, "Field and

LABORATORY

Laboratory Tests"

FIELD

2. Subsurface Exploration and Foundation Report, Vol. III, Part 2, "Field
Explorations, Dam, Reservoir, and Spillway"

POST-CONSTRUCTION SURVEYS OF DAM

None available.

BORROW SOURCES

Drawing 4042 C-426-447 "Borrow Areas; Plans and Sections"

MONITORING SYSTEMS

Drawing 4042 C-426-463 "Weir Installations; Downstream Toe of Dam"
Continuous monitoring of the system is provided by D'Appolonia Consulting Engineers, Inc.

MODIFICATIONS

None.

HIGH POOL RECORDS

Available at Keystone Power Station.

POST CONSTRUCTION ENGINEERING
STUDIES AND REPORTS

PRIOR ACCIDENTS OR FAILURE OF DAM
DESCRIPTION
REPORTS

Not applicable.

MAINTENANCE
OPERATION
RECORDS

Available at Keystone Power Station.

ITEM	REMARKS	ID #	PA-275	SHEET 4
------	---------	------	--------	---------

SPILLWAY PLAN Drawings 4042 C-426-470, 471

SECTIONS Drawings 4042 C-426-472, 473, 474

DETAILS Drawings 4042 C-426-475, 475, 477, 478, 479

OPERATING EQUIPMENT
PLANS & DETAILS

Drawing 4042 C-426-446 "Piezometer Piping and Flow Diagram"
Drawing 4042 C-426-460 "Piping-Valve Chamber"
Drawing 4042 C-426-462 "Electrical"

NDI# PA-275

CHECK LIST ID # PennDER# 3-28

HYDROLOGIC AND HYDRAULIC
ENGINEERING DATA

DRAINAGE AREA CHARACTERISTICS: 21 square miles.

ELEVATION TOP NORMAL POOL (STORAGE CAPACITY): 1077 feet; 27,000 acre-feet.

ELEVATION TOP FLOOD CONTROL POOL (STORAGE CAPACITY): Not known.

ELEVATION MAXIMUM DESIGN POOL: 1090 feet; 40,000 acre-feet.

ELEVATION TOP DAM: 1093 feet.

SPILLWAY DATA:

- a. Crest Elevation 1093 feet.
- b. Type Concrete with ogee crest.
- c. Weir Length 180 feet.
- d. Channel Length ≈1700 feet.
- e. Location Spillover Approx. 1 mile upstream along southeast embank-
- f. Number and Type of Gates None. ment.

OUTLET WORKS:

- a. Type 7.0' x 7.0' concrete box culvert.
- b. Location Upstream of left (southeast) abutment.
- c. Entrance Inverts 24" C.I.P. feeds 7' x 7' culvert at ele. 1015.
- d. Exit Inverts 7' x 7' box culvert at ele. 993.5.
- e. Emergency Draindown Facilities Above.

HYDROMETEOROLOGICAL GAGES:

- a. Type Not known.
- b. Location Keystone Generating Facility.
- c. Records at Keystone Generating Facility.

MAXIMUM NON-DAMAGING DISCHARGE: Not known.

APPENDIX B.

CHECK LIST - VISUAL INSPECTION

CHECK LIST
VISUAL INSPECTION
PHASE 1

DAM NAME Keystone Station Dam COUNTY Armstrong STATE Pennsylvania ID # NDI# PA-275
TYPE OF DAM Earthfill HAZARD CATEGORY High
DATE(S) INSPECTION 15 May 78 WEATHER Light Rain TEMPERATURE 50°-60°
POOL ELEVATION AT TIME OF INSPECTION 1077.25 M.S.L. TAILWATER AT TIME OF INSPECTION 1005 M.S.L.

INSPECTION PERSONNEL:

GAI

B. Mihalcin

J. Nairn

K. Khilji

D. Bonk

Penelec

R. Gallus - Engr.

R. Kovack

DER (Penna)

T. Dreier (Engr)

F. Anton (Engr)

B. Mihalcin

RECORDER

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	None.	
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	None.	
SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	None.	
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	No Problem.	
RIPRAP FAILURES	None.	

SURFACE CRACKS

None.

UNUSUAL MOVEMENT OR
CRACKING AT OR BEYOND
THE TOE

None.

SLOUGHING OR EROSION OF
EMBANKMENT AND ABUTMENT
SLOPES

None.

VERTICAL AND HORIZONTAL
ALIGNMENT OF THE CREST

No Problem.

RIPRAP FAILURES

None.

VISUAL EXAMINATION OF OBSERVATIONS REMARKS OR RECOMMENDATIONS

JUNCTION OF EMBANKMENT
AND ABUTMENT, SPILLWAY
AND DAM

Minor sloughing on the right abutment near the elevation of the berm on the downstream face of the dam.

ANY NOTICEABLE SEEPAGE

None apparent - Occasional drizzle during inspection.
One seep located on right abutment at bench level; apparent cause of minor sloughing (just outside contact with downstream embankment on abutment).

STAFF GAGE AND RECORDER

Staff gage on intake. Recorder at station and pressure transducer in outlet tower.
Weir located in settling basin to monitor stream flow.

DRAINS

Catch basins located on bench carry away surface runoff.
Toe drain and drainage ditch with weir empties into settling basin.

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
-----------------------	--------------	----------------------------

CRACKING AND SPALLING OF
CONCRETE SURFACES IN
OUTLET CONDUIT

None observed.
Four feet of water at concrete box culvert outlet.

INTAKE STRUCTURE

Excellent condition - protected by logs to keep boats a safe distance away.

OUTLET STRUCTURE

Concrete box culvert in apparent excellent condition.

OUTLET CHANNEL

100 feet long rock lined stilling basin followed by 150 feet of unlined natural channel.
Weir panels are eroded and needing repair or replacement.

EMERGENCY GATE

Outlet is gated at intake tower.

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
-----------------------	--------------	----------------------------

CONCRETE WEIR

Upstream and downstream ogee spillways are in apparent good condition.

APPROACH CHANNEL

Concrete approach to ogee.

DISCHARGE CHANNEL

Channel cut in rock with vertical slopes. Some rockfalls have been repaired with concrete patches. Vertical walls are secured at numerous places with anchors. Excellent condition.

BRIDGE AND PIERS

Downstream overpass bridge across spillway channel in apparent excellent condition.

GATED SPILLWAY ID # PA-275 SHEET 5

REMARKS OR RECOMMENDATIONS

OBSERVATIONS

VISUAL EXAMINATION OF

CONCRETE SILL

N/A

APPROACH CHANNEL

N/A

DISCHARGE CHANNEL

N/A

BRIDGE AND PIERS

N/A

GATES AND OPERATION

EQUIPMENT

N/A

VISUAL EXAMINATION OBSERVATIONS REMARKS OR RECOMMENDATIONS

MONUMENTATION/SURVEYS

Survey monument observed on both abutments.

OBSERVATION WELLS

None - Relief wells located at toe.

WEIRS

2 weirs:

1. Located at downstream end of stilling basin. Used to measure stream flow.
2. Located at approximate middle of right side of stilling basin. Used to measure flow emanating from relief wells and toe drains.

PIEZOMETERS

Located at 2 levels on downstream embankment. Weirs are read monthly. All are operable and in apparent good shape. Piezometer at toe near relief wells displaying artesian water condition and liberating gas. Piezometers rise approximately 2 feet out of ground.

OTHERS

REMARKS OR RECOMMENDATIONS

VISUAL EXAMINATION OF

OBSERVATIONS

SLOPES

Gentle to moderate and in good shape.

SEDIMENTATION

Not apparent.

Water level at 17 feet below crest of dam.

CONDITION
(OBSTRUCTIONS,
DEBRIS, ETC.)

Meandering stream through broad valley to road embankment.

SLOPES

Gentle to moderate.

APPROXIMATE NO.
OF HOMES AND
POPULATION

First house downstream is at elevation of road embankment and would be affected by failure.

APPENDIX C
HYDRAULICS/HYDROLOGY

SUBJECT DAM SAFETY INSPECTION

KEYSTONE STATION DAM

BY DLB DATE 5-19-78 PROJ. NO. 78-501-275

D. BY KW DATE 5/23/78 SHEET NO. 1 OF 16



Engineers • Geologists • Planners
Environmental Specialists

KEYSTONE STATION DAM

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC

DAM LOCATION - ELDERTON QUADRANGLE
DRAINAGE AREA - PLUMVILLE QUADRANGLE
RURAL VALLEY QUADRANGLE

DAM STATISTICS

MAXIMUM HEIGHT OF DAM = 100' (FIELD OBSERVATION)

DRAINAGE AREA = 20.6 sq mi (PLANIMETERED)

STORAGE CAPACITY = 27,000 AC-FT (REF: DRAWG C-426-482)
GILBERT ASSOCIATES, INC.

SIZE CLASSIFICATION

DAM SIZE - LARGE (REF 1, TABLE 1)

STANDARD DESIGN FLOOD (SDF) (REF 1, TABLE 2)

HAZARD RATING - HIGH (BASED ON FIELD OBSERVATION)

REQUIRED SDF - PMF (REF 1, TABLE 3)

POSSIBLE LOSS OF LIFE GREATER THAN 3

REF 1: "RECOMMENDED GUIDELINES FOR SAFETY INSPECTION OF DAMS"
DEPT OF ARMY, APPENDIX D

SUBJECT DAM SAFETY INSPECTION
KEYSTONE STATION DAM
DLB DATE 5-19-78 PROJ. NO. 78-501-275
CHKD. BY KWU DATE 5/23/78 SHEET NO. 2 OF 16



$$\text{PMF (PEAK FLOW) / AREA} = (1,200 \text{ sq. mi}) \quad (\text{SHEET 13 OF 15})$$


$$\text{PMF} = (1,200 \text{ CFS / mi}^2)(20.6 \text{ mi}^2)$$

$$\text{PMF} = \text{SDF} = 24,720 \text{ CFS}$$

DEVELOP INFLOW HYDROGRAPH

$$\text{MAXIMUM INFLOW } Q_{\text{IMAX}} = 24,720 \text{ CFS}$$

$$\text{TOTAL TIME OF FLOW} = 58 \text{ HRS} \quad (\text{SHEET 14 OF 15})$$



THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG

SUBJECT DAM SAFETY INSPECTION

KEYSTONE STATION DAM

DLB DATE 7-5-78 PROJ. NO. 78-501-275

CHKD. BY _____ DATE _____ SHEET NO. 3 OF 16



Engineers • Geologists • Planners
Environmental Specialists

VOLUME OF INFLOW FROM HYDROGRAPH

$$\begin{aligned} V &= \frac{1}{2} (Q_{\text{MAX}}) (\text{TIME}) \\ &= \frac{1}{2} (24,720 \text{ CFS}) (58 \text{ HRS}) (3600 \text{ SEC/HR}) (1 \text{ ACRE} / 43,560 \text{ FT}^2) \\ &= 59,246 \text{ ACRE-FEET} \end{aligned}$$

DETERMINE THE AVERAGE RAINFALL IN INCHES REQUIRED TO PRODUCE THE VOLUME ABOVE.

$$\frac{(59,246 \text{ AC-FT})}{(20.6 \text{ SQ. MI})} (1 \text{ SQ. MI} / 640 \text{ ACRES}) (12 \text{ IN/FT}) = 53.9 \text{ INCHES}$$

VOLUMES PRODUCED BY RAINFALLS IN EXCESS OF 26 INCHES ARE TO BE RECALCULATED USING 26 INCHES AS AN UPPER BOUND.

$$(26 \text{ INCHES}) (20.6 \text{ SQ. MI}) (640 \text{ ACRES/SQ. MI}) (1 \text{ FT} / 12 \text{ IN}) = 28,565 \text{ AC-FT}$$

$$\text{VOLUME OF INFLOW (RECALCULATED)} = 28,565 \text{ AC-FT}$$

NOTE: Q_{MAX} REMAINS CONSTANT

FLOOD DURATION DECREASES IN ACCORDANCE WITH THE DECREASE IN INFLOW VOLUME

$$\begin{aligned} \text{EQUIVALENT STORM DURATION} &= (28,565 \text{ AC-FT}) (2 (43,560 \text{ FT}^2/\text{AC})) (3600 \text{ SEC/HR}) (24,720 \text{ CFS}) \\ &= 28 \text{ HRS} \end{aligned}$$

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC

SUBJECT DAM SAFETY INSPECTION

KEYSTONE STATION DAM

DLB

DATE

5-19-78

PROJ. NO.

78-501-275

CHKD. BY

KHH

DATE


5/23/78

SHEET NO.

4

OF

16



CONSULTANTS, INC.

Engineers • Geologists • Planners
Environmental Specialists

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG

SPILLWAY

(UPSTREAM WEIR)

NOTE: ELEVATIONS TAKEN

FROM DRAWG C-426-470

(GILBERT ASSOCIATES, INC)

SPILLWAY CREST EL 1077

P=7'

POOL BOTTOM EL 1070

STILLING
BASIN

Top of VERTICAL WALL EL 1090.0

180ft

SPILLWAY CREST EL 1077

NOTE: WIDTH OF CREST WAS

SCALED FROM DRAWG C-426-470

SUBJECT DAM SAFETY INSPECTION
KEYSTONE STATION DAM

DLB DATE 5-19-78 PROJ. NO. 78-501-275

CHKD. BY KWH DATE 5/23/78 SHEET NO. 5 OF 16



Engineers • Geologists • Planners
Environmental Specialists

SPILLWAY CAPACITY (UPSTREAM WEIR)

$$Q = C L H^{3/2} \quad (\text{REF 2, EQ 21-121})$$

H = HEAD

H_{MAX} = MAXIMUM POSSIBLE HEAD

(SHEET 3)
"

$$= (1090 - 1077)^*$$

$$= 13.0 \text{ FT}$$

L = CREST LENGTH

$$= 180$$

C = DISCHARGE COEFFICIENT

FROM REF 2, FIG 21-67

$$P/H_D = 7/13 = 0.54$$

$$\therefore C = 3.82$$

$$Q_{\text{MAX}} = (3.82)(180')(13.0')^{3/2}$$

$$Q_{\text{MAX}} = 32,229 \text{ cfs}$$

NOTE: ELEVATION 1090 (TOP OF SPILLWAY WALL) IS USED RATHER THAN ELEVATION 1093 (TOP OF DAM) BECAUSE IT IS ASSUMED THAT ONCE THE SPILLWAY WALLS ARE OVERTOPPED THE EFFECTS WILL BE UNKNOWN & UNPREDICTABLE

REF 2: "STANDARD HANDBOOK FOR CIVIL ENGINEERS" by F.S. MERRITT

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC

SUBJECT DAM SAFETY INSPECTION

KEYSTONE STATION DAM

DLB DATE 6-12-78 PROJ. NO. 78-501-275

CHKD. BY JPN DATE 6-16-78 SHEET NO. 6 OF 16



Engineers • Geologists • Planners
Environmental Specialists

SPILLWAY CAPACITY (DOWNSTREAM WEIR)

$$Q = CLH^{3/2} \quad (\text{REF 2, EQ 21-121})$$

$$H = (H_0 + V^2/2g)$$

REF:

DWA C-426-475 $H_0 = \text{MAXIMUM POSSIBLE ELEVATION HEAD}$
 $= (1076 - 1052.75) = 23.25 \text{ FT}$

$V_0 = \text{VELOCITY HEAD}$

$$Q = VA \quad \text{OR} \quad V = Q/A$$

WHERE $Q = 32,229 \text{ CFS}$ (SHEET 5)
(AREA OF FLOW @ UPSTREAM WEIR) $= A = (180 \text{ FT})(7.0 \text{ FT}) = 1260 \text{ FT}^2$
 $V = 25.6 \text{ FPS}$

$$H = [(23.) + (25.6)^2/2(32.2)] = 33.2$$

$$L = \text{LENGTH OF CREST} = 60 \text{ FT}$$

$C = \text{DISCHARGE COEFFICIENT}$

FROM REF 2, FIG 21-67

$$P/H_0 = 4'/23.25' = 0.172$$

$$\therefore C = 3.40$$

$$Q_{\text{MAX}} = (3.4)(60')(33.2)^{3/2} = 39,024 \text{ CFS}$$

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG

SUBJECT DAM SAFETY INSPECTION
KEYSTONE STATION DAM
BY DLB DATE 6-12-78 PROJ. NO. 78-501-275
CHKD. BY JPN DATE 6-16-78 SHEET NO. 7 OF 16



Engineers • Geologists • Planners
Environmental Specialists

39,024 CFS > 32,229 CFS

THUS THE CAPACITY OF THE DOWNSTREAM WEIR
IS GREATER THAN THAT OF THE UPSTREAM WEIR AND
CONSEQUENTLY THE MAXIMUM FLOW OVER THE UPSTREAM WEIR
WILL BE SAFELY ROUTED DOWNSTREAM WITHOUT OVERTOPPING
THE CHANNEL WALLS.


THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG

SUBJECT DAM SAFETY INSPECTION
KEYSTONE STATION DAM
 DLB DATE 5-19-78 PROJ. NO. 78-501-275
 CHKD. BY KMM DATE 5/23/78 SHEET NO. 8 OF 16

gai
 CONSULTANTS, INC.
 Engineers • Geologists • Planners
 Environmental Specialists

DISCHARGE CAPACITY OF OUTLET WORKS

INTAKE TOWER



NOTE: ALL DIMENSIONS AND
 ELEVATIONS TAKEN FROM
 DRWG C-426-460 AND
 DRWG C-426-461
 (GILBERT ASSOCIATES)

24" ϕ C.I. INTAKE PIPE EL 1015 (ACTUAL ϕ AT 1014.75)

FLOW AT INTAKE IS UNDER PRESSURE WITHIN THE 24" ϕ C.I. PIPE
 UNTIL IT DISCHARGES INTO THE BOX CULVERT WHERE IT THEN
 BECOMES OPEN CHANNEL FLOW.

CONSIDER DISCHARGE OF 24" ϕ C.I. PIPE

USE BERNOULLI'S EQUATION

(REF 2, EQ 21-12)

$$Z_1 + P_1/\omega + V_1^2/2g = Z_2 + P_2/\omega + V_2^2/2g + h_f + h_e$$

THIS PAGE IS BEST QUALITY PRACTICABLE
 FROM COPY FURNISHED TO DDG

SUBJECT DAM SAFETY INSPECTION
KEYSTONE STATION DAM
 DLB DATE 5-19-78 PROJ. NO. 78-501-275
 CHKD. BY KLU DATE 5/23/78 SHEET NO. 9 OF 16

gai
 CONSULTANTS, INC.
 Engineers • Geologists • Planners
 Environmental Specialists

ASSUME DATUM @ EL 1015

Z_1 = HEIGHT OF INLET ABOVE DATUM = 0
 Z_2 = " " OUTLET " " = 0
 P_1/w = PRESSURE HEAD AT INLET (1093-1015) = 78'
 P_2/w = " " " OUTLET = 0
 V_1 = VELOCITY AT INLET = 0
 V_2 = " " OUTLET = SOLVE FOR
 g = = 32.2 FT/SEC²

$$h_f = f \frac{L V^2}{2gD} \quad (\text{REF 2, EQ 21-30})$$

L = LENGTH OF CONDUIT = 6'

DRAWG C-426-460
 SECTION A-A

D = DIAMETER OF CONDUIT = 2'

f = FRICTION COEFFICIENT

FOR $E = 0.00085$ (REF 2, TABLE 21-3)
 $E/D = 0.000425$
 $R = 1.0 \times 10^7$

$f \approx 0.017$ (REF 2, FIG 21-19)

SUBJECT DAM SAFETY INSPECTION

KEYSTONE STATION DAM

DLB DATE 5-19-78 PROJ. NO. 78-501-275

CHKD. BY KAN DATE 5/23/78 SHEET NO. 10 OF 16



Engineers • Geologists • Planners
Environmental Specialists

$$h_e = K_E \frac{V^2}{2g} \quad (\text{REF 2, EQ 21-42})$$

h_e = HEAD LOSS DUE TO ENTRANCE AND/OR EXIT FIXTURES

CONSIDER 1 GATE VALVE ON BOTH PIPE ENDS

$$K_E = 0.2 \quad (\text{REF 2: TABLE 21-8})$$

SOLVE BERNOULLI'S EQUATION

$$0 + 78' + 0 = 0 + 0 + \frac{V^2}{(2)(32.2 \text{ ft/s}^2)} + \frac{(0.017)(6')(V^2)}{(2)(32.2)(2)} + \frac{2(0.2)(V^2)}{2(32.2)}$$

$$78' = 0.016V^2 + 0.001V^2 + 0.006V^2$$

$$78' / 0.023V^2$$

$$V = 58.2 \text{ FPS}$$

$$Q_{24"} = VA = (58.2)(\pi)(1)^2$$

$$Q_{24"} = 183 \text{ CFS}$$

$$Q_{in} = Q_{out}$$

$$\text{DISCHARGE AT CULVERT OUTLET (MAXIMUM)} = 183 \text{ CFS}$$

SUBJECT DAM SAFETY INSPECTION
KEYSTONE STATION DAM
BY DLB DATE 5-19-78 PROJ. NO. 78-501-275
CHKD. BY KNL DATE 5/23/78 SHEET NO. 11 OF 12



MAXIMUM DISCHARGE OVER SPILLWAY = 32,229 CFS
MAXIMUM DISCHARGE THRU PIPE = 183 CFS

32,412 CFS

PMF (PEAK INFLOW) = 24,720 CFS

$24,720 \text{ CFS} < 32,412 \text{ CFS}$

CONCLUSION: KEYSTONE STATION DAM WILL PASS THE PMF
AS PRESCRIBED BY THE GRAPHS SUPPLIED
BY THE CORPS OF ENGINEERS.

PENELEC FILES CONTAIN A GRAPH (SHEET 16) TITLED
RESERVOIR ROUTING CHART. ON THIS GRAPH ARE PLOTTED
FIVE POINTS WHICH ARE LABELED 100yr, 1000yr, 10,000yr
STD. PROJ., AND MAXIMUM PROBABLE FLOOD

FROM THIS GRAPH

PMF (PEAK INFLOW) = 33,000 CFS

$33,000 \text{ CFS} > 32,412 \text{ CFS}$

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC

SUBJECT DAM SAFETY INSPECTION
KEYSTONE STATION
BY DLB DATE 5-23-78 PROJ. NO. 78-501-275
CHKD. BY KWK DATE 5/23/78 SHEET NO. 12 OF 16



CONSIDER INFLOW RELATIVE TO BOTH OUTFLOW AND STORAGE

USING SHORT-CUT METHOD AS RECOMMENDED BY NAD

$$P = \frac{\text{MAXIMUM TOTAL DISCHARGE}}{\text{PMF PEAK INFLOW}} = \frac{32,412}{33,000} = 0.982$$

$$1-P = \frac{\text{REQUIRED RESERVOIR STORAGE}}{\text{VOLUME OF INFLOW HYDROGRAPH}} = 0.018$$

STORM DURATION = 33 HRS

(REF: DRAWG C-426-482
RESERVOIR ROUTING CHART)

VOLUME OF INFLOW HYDROGRAPH =

$$= \frac{1}{2} (33,000 \text{ cfs}) (33 \text{ HRS}) (3600 \text{ SEC/HR}) (1 \text{ ACRE/43560 FT}^2) = 45,000 \text{ AC-FT}$$

$$\text{STORAGE REQUIRED} = (45,000) (0.018) = 810 \text{ AC-FT}$$

$$\text{STORAGE AVAILABLE} = (40,000 - 27,000) \text{ AC-FT} = 13,000 \text{ AC-FT}$$

(REF: DRAWG C-426-482
"STORAGE AREA CURVE"
GILBERT ASSOCIATES, INC.)

SUBJECT

DAM SAFETY INSPECTION

KEYSTONE STATION DAM

DLB

DATE

5-23-78

PROJ. NO.

78-501-275

CHKD. BY

KMU

DATE

5/23/78

SHEET NO.

13

OF

16



Engineers • Geologists • Planners
Environmental Specialists

STORAGE REQ'D < STORAGE AVAILABLE
810 AC-FT < 13,000 AC-FT

CONCLUSION: KEYSTONE STATION DAM HAS ADEQUATE
DISCHARGE AND STORAGE CAPACITY TO
ACCOMMODATE THE PMF

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC


CODER BOOK COMPANY, INC. NEWBOD, MASSACHUSETTS



CFS/M^2


PMF Peak Flow / AREA

NO. 4123 LOGARITHMIC, 5 BY 5 1/2 INCH CYCLES.



THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG


TOTAL TIME IN HOURS



THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC

Revised 10/1/60


THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG




APPENDIX D
PHOTOGRAPHS

PHOTOGRAPH 1 Panoramic view of the Keystone Station Dam, the area immediately downstream, and the reservoir area. Note the wide open valley just downstream of the embankment.

PHOTOGRAPH 2 View from the right abutment showing the crest of the Keystone Station Dam embankment and the area just downstream. The rock toe is visible near the right side of the photograph.



1






2

PHOTOGRAPH 3 View looking downstream from the crest of the embankment showing the first downstream improvement, a road which passes across the valley approximately 1/2 mile downstream as well as some dwellings that are located just downstream of the dam.

PHOTOGRAPH 4 View looking upstream from the area just downstream of the discharge outlet of the facility.

PHOTOGRAPH 5 View of the V-notched weir located just downstream of the outlet to the Keystone Dam.

PHOTOGRAPH 6 Close-up view of a piezometer located a couple hundred feet to the right of the Keystone Reservoir outlet at the toe of the dam. Note that the water was issuing from the top of the piezometer indicating that there is some head at this point. Also note the line of relief wells which have been installed at the toe of the embankment.




PHOTOGRAPH 7 View of the toe drain of the embankment and the relief wells mentioned in the previous photograph. The weir in the center of the photograph gauges flow from the area of the right abutment and any flow which might be discharging through the relief wells.


PHOTOGRAPH 8 This is a view of the spillway at the Keystone Station Reservoir located approximately one mile upstream of the Keystone Reservoir embankment.

PHOTOGRAPH 9 This is a view of the interior of the gate house at the Keystone Reservoir. The gate controls in the center of the photograph are used to raise sluice gates on the discharge system for the reservoir.


PHOTOGRAPH 10 View taken from the road located approximately 1/2 mile downstream showing the Keystone Dam embankment in the background.




8



10



7



9

APPENDIX E

GEOLOGY

The Keystone Station Dam is located near the axis of a syncline between the Roaring Run and the Dutch Run Anticlines. Dominant lithologies in the area are characterized as sandstones, shales, limestones, and a few thin coal beds of the Pennsylvanian age, Conemaugh Formation. Within the reservoir area, and unconformably overlying the sedimentary rocks, there are many high level river terrace deposits. The Keystone Station Generating Plant is located on one of these terrace deposits which are characterized as fluvial sands and gravels containing some layers of silt and clay as well as numerous boulders.


APPENDIX F

FIGURES

LIST OF FIGURES

<u>Figure</u>	<u>Description</u>
1	Plot Plan
2	Stability Analysis
3	Earth Dam Plan
4	Earth Dam Cross Sections
5	Intake Tower Piping Details
6	Intake Tower Grading Sections
7	Spillway Channel
8	Reservoir Hydraulic Data

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC



INTAKE TOWER

DAM


ACCESS ROAD


RELOCATED

ROUTE 210

RESER
RAILWAY ELEV

PLUM CREEK TOWNSHIP
ARMSTRONG COUNTY, PENNS





PLUM CREEK TOWNSHIP
ARMSTRONG COUNTY, PENNSYLVANIA

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC


KEYSTONE STATION OWNERS GROUP
ATLANTIC CITY ELECTRIC COMPANY
BALTIMORE GAS AND ELECTRIC COMPANY
DELAWARE POWER & LIGHT COMPANY
JERSEY CENTRAL POWER & LIGHT COMPANY
PENNSYLVANIA POWER & LIGHT COMPANY
PHILADELPHIA ELECTRIC COMPANY
PUBLIC SERVICE ELECTRIC AND GAS COMPANY

REVISIONS			
NO.	DATE	BY	APPROVAL

KEYSTONE STATION OWNERS GROUP			
KEYSTONE STATION		UNITS 1 & 2	
Plum Creek North Branch Reservoir Area			
Dam, Intake Tower and Spillway			
Pilot Plan			
READING, PENNA.	GILBERT ASSOCIATES, INC.		NEW YORK, N.Y.
ENGINEERS AND CONSULTANTS			
DESIGNED BY		CHECKED BY	
DRAWN BY		APPROVED BY	
SCALE		DATE	
1"=400'		4042 C-426-440	
SCALE	WORK ORDER	DATE	DESIGNED BY

FIGURE 1

Notation as shown
here is typical for
all sections.



MAXIMUM SECTION

TYPICAL SECTION

Factor of Safety against shear
for $\phi = 0$ and $\phi = 10$


N = Force normal to circle at any point
 T = Force tangent to circle at any point
 L = Length of circle
 ϕ = Shear angle of material
 C = Cohesion of material

- CASE I: Construction Condition.
Reservoir Empty.
Foundation partially consolidated.
- CASE II: Sudden Drawdown Condition.
Drawdown from Nor.Pool Elev. 1077 to
Assumed Min.Pool Elev. 1040.
No T.W. Condition.
- CASE III: Normal Operating Condition.
H.W. Elev. 1077.
No T.W. Condition.

NOTE:-

In Case II and Case III the foundation is
taken as more fully consolidated than Case I,
but as not having reached full consolidation.

(THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG)



TYPICAL SECTION


SUMMARY - CIRCLE ANALYSES-

Section	Circle	Case	X	Y	R	Σ N (lb)	Σ L	Σ T	F _s
Maximum	1	II	175.7	25.0	195.0	315,970	117,180	297,500	1.49
	2	III	145.3	27.5	197.5	438,890	151,180	344,940	1.61
Typical	3	I	176.1	20.4	150.4	153,030	85,790	240,900	1.41
-	4	II	175.6	100.2	100.2	304,170	100,810	305,980	1.31
-	5	I	183.8	136.6	241.6	300,530	123,410	336,500	1.26
-	6	III	183.8	136.6	241.6	333,170	123,410	337,950	1.35
Abutment	7	I	104.1	39.8	102.8	133,090	54,130	116,480	1.51
-	8	II	112.1	24.8	81.8	70,470	41,970	84,030	1.41
-	9	I	77.2	14.6	77.6	107,430	41,330	104,810	1.46
-	10	III	77.2	14.6	77.6	113,670	41,330	104,810	1.48

PROPERTIES OF MATERIAL

Material	Unit Weight (pcf)	Saturated Weight (pcf)	Buoyant Weight (pcf)
A Selected Rolled F-11	110	131.5	70
	110	131.5	70
B Detritus Material	110	131.5	70
	110	131.5	70
C Silty Foundation	110	131.5	70
	110	131.5	70
D Clay Foundation	110	131.5	70
	110	131.5	70


All Cases



TYPICAL SECTION

ABUTMENT SECTION

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG



TYPICAL SECTION

ABUTMENT SECTION

PROPERTIES OF MATERIALS


Material	Moist Weight W ₁	Saturated Weight W ₂	Buoyant Weight W ₃	γ	tan δ	C
A Selected Rolled Fill	115	131.5	70	114	445	400
B Heavy Sub Material	110	—	70	40	840	0
C Case I	115	131.5	70	10	174	150
C Case II	115	131.5	70	20.5	374	150
C Case III	115	131.5	70	15	168	150
C Case IV	115	131.5	70	35	167	650
D Case I	115	131.5	70	12	115	650
D Case II	115	131.5	70	12	115	650

(1) 10' for Abutment Section
(2) 30' for Abutment Section

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG

KEYSTONE STATION OWNERS GROUP
ATLANTIC CITY ELECTRIC COMPANY
BAY TOWNSHIP AND ELECTRIC COMPANY
BETHLEHEM POWER & LIGHT COMPANY
CENTRAL POWER & LIGHT COMPANY
PENNSYLVANIA POWER & LIGHT COMPANY
PHILADELPHIA ELECTRIC COMPANY
PUBLIC SERVICE ELECTRIC AND GAS COMPANY

REVISIONS	
NO.	DATE
KEYSTONE STATION OWNERS GROUP	
KEYSTONE STATION UNITS 1 & 2	
Pilot Creek-North Branch Reservoir Area	
Extra Dam	
Stability Analysis	
DESIGNED BY	GILBERT ASSOCIATES, INC.
ENGINEERS AND CONSULTANTS	NEW YORK, N.Y.
DATE	11-1-51
BY	W. H. S. / J. H. S.
CHECKED BY	W. H. S. / J. H. S.
APPROVED BY	W. H. S. / J. H. S.
SCALE	1"=60'
WORK ORDER	4042
DATE	C-426-443
DRAWING	
REV	



(SPILLWAY EL. 1077
NORMAL WATER LEVEL)

CLOSE
TO
DRAINAGE
DITCHES

20
1
1

3

a

MON. A.
N. 8555.47
W. 45305.21
EL. 1156.48

THEORETICAL
TOE OF DAM

(R.I.P. R.A.D.)

GUARD RAIL

12' SERVICE ROAD
EL. 1034.00

(GRASSED)

3' WIDE ASPHALT
GUTTER

CATCH BASIN
EL. 1047.75

(GRASSED)

12" CORR. PIPE - LAY WITH OPEN JOINTS

EL. 1018.00

COLLECTION
DITCH

1" PRESSURE RELIEF
HOLES, 12" C.C.
54 HOLES REQUIRED

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG









REFERENCES:
C-420-446 SECTIONS A, B, C
C-420-461 SECTIONS D, E, F, G

MEASUREMENTS
TO BE PLACED ON
SP ALL DRAINAGE
DITCHES FROM D.A.
SEE DWG. C-420-4

GAGE BOARD
CALIBRATED
TENTHS INCH
OF FEET

WOODEN WEIR
TO BE PLACED ON
SP ALL DRAINAGE
DITCHES FROM D.A.
SEE DWG. C-420-4

H



NOTE:
3" Dia. auger hole to first, followed by placing 12" Dia. Corr. Metal Pipe & hold to be drilled past the Corr. Metal Pipe.






FIGURE 4

THIS
FROM



SECTIONAL PLAN
(ABOVE ELEV. 1020.5)

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC




SECTION A-A


24", Class 150, Schedule 80 Steel Pipe, with
Welding Neck Flanges A S A Drilling, with
Collars Welded to Pipe. Bolts to be Placed
And Heads Welded to the Backs of Bolt
Flanges Prior to Concrete Placement.
Installed With Bolt Holes Straddling the Vertical
And Horizontal Center Lines. Both Ends of
Pipe to be Installed Identical.

Page 1


All Five (5) Coats Printed with Two Coats and One
Finish Coat of Red Oxide Paint. First Coat Red
Surface Number 9374, Second Coat 9365, All Other
Under Water to Red Oxide Finish Coat of Red is
Number 9376, All Other Steel to Receive a Finish
Coat of Red is Number 961.



SECTIONAL PLAN F-F




SECTION E-F




SECTION 5-2



SECTION 2-1





SECTION 8-4




SECTION C-2


DESCRIPTION				
NO.	DATE	BY	CHKD	APPROVED, S.
REVISIONS				

[illegible]




THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG





STA 3+30.00 SECTION E-E



STA 1+52.00 SECTION G-G


NOTE:
Existing Grade as noted on this
Drawing Represents the Limits
of the First Stage Excavation.
First Stage Excavation shown
on Drawing No. C-426-441


THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG

KEYSTONE STATION OWNERS GROUP
ATLANTIC CITY ELECTRIC COMPANY
BALTIMORE GAS AND ELECTRIC COMPANY
DELAWARE POWER & LIGHT COMPANY
JERSEY CENTRAL POWER & LIGHT COMPANY
PENNSYLVANIA POWER & LIGHT COMPANY
PHILADELPHIA ELECTRIC COMPANY
PUBLIC SERVICE ELECTRIC AND GAS COMPANY

KEYSTONE STATION OWNERS GROUP			
KEYSTONE STATION		UNITS 1 & 2	
Pine Creek-North Branch Reservoir Area			
Intake Tower			
Grading Sections			
DESIGNED PENNA.	GILBERT ASSOCIATES, INC. ENGINEERS AND CONSULTANTS		NEW YORK N.Y.
DRAWN J.M.S.	CHECKED J.M.S.	APPROVED J.M.S.	DATE 10/1/55
SCALE 1"=20'	WORK ORDER 4042	DWG C-426-461	REV 01

FIGURE 6





THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC

PROFILE
SCALE HOR. 1"=60'
VERT. 1"=10'


KEYSTONE STATION OWNERS GROUP
ATLANTIC CITY ELECTRIC COMPANY
BALTIMORE GAS AND ELECTRIC COMPANY
DELAWARE POWER & LIGHT COMPANY
EDISON - CENTRAL POWER & LIGHT COMPANY
PENNSYLVANIA POWER & LIGHT COMPANY
PHILADELPHIA ELECTRIC COMPANY
PUBLIC SERVICE ELECTRIC AND GAS COMPANY

KEYSTONE STATION OWNERS GROUP			
KEYSTONE STATION		UNITS 1 & 2	
Plan, Grading, and Structural Design			
S. H. H. Channel and Control Wall			
1940 Grading Plan and Profile			
GILBERT ASSOCIATES, INC.		NEW YORK, N.Y.	
ENGINEERS AND CONSULTANTS			
DRAWING	4042	C-426-470	SCALE
WORK ORDER	REV	DATE	BY




FIGURE 7

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDG




FLOOD FREQUENCY CURVES



RESERVOIR ROUTING EFFECTS
DESIGN FLOOD



THIS PAGE IS BEST QUALITY PRACTICE
FROM COPY FURNISHED TO DDO



KEYSTONE STATION OWNERS GROUP

ATLANTIC CITY ELECTRIC COMPANY
BALTIMORE GAS AND ELECTRIC COMPANY
DELAWARE POWER & LIGHT COMPANY
JERSEY CENTRAL POWER & LIGHT COMPANY
PENNSYLVANIA POWER & LIGHT COMPANY
PHILADELPHIA ELECTRIC COMPANY
PUBLIC SERVICE ELECTRIC AND GAS COMPANY

REVISIONS 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100 101 102 103 104 105 106 107 108 109 110 111 112 113 114 115 116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131 132 133 134 135 136 137 138 139 140 141 142 143 144 145 146 147 148 149 150 151 152 153 154 155 156 157 158 159 160 161 162 163 164 165 166 167 168 169 170 171 172 173 174 175 176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195 196 197 198 199 200 201 202 203 204 205 206 207 208 209 210 211 212 213 214 215 216 217 218 219 220 221 222 223 224 225 226 227 228 229 230 231 232 233 234 235 236 237 238 239 240 241 242 243 244 245 246 247 248 249 250 251 252 253 254 255 256 257 258 259 260 261 262 263 264 265 266 267 268 269 270 271 272 273 274 275 276 277 278 279 280 281 282 283 284 285 286 287 288 289 290 291 292 293 294 295 296 297 298 299 300 301 302 303 304 305 306 307 308 309 310 311 312 313 314 315 316 317 318 319 320 321 322 323 324 325 326 327 328 329 330 331 332 333 334 335 336 337 338 339 340 341 342 343 344 345 346 347 348 349 350 351 352 353 354 355 356 357 358 359 360 361 362 363 364 365 366 367 368 369 370 371 372 373 374 375 376 377 378 379 380 381 382 383 384 385 386 387 388 389 390 391 392 393 394 395 396 397 398 399 400 401 402 403 404 405 406 407 408 409 410 411 412 413 414 415 416 417 418 419 420 421 422 423 424 425 426 427 428 429 430 431 432 433 434 435 436 437 438 439 440 441 442 443 444 445 446 447 448 449 450 451 452 453 454 455 456 457 458 459 460 461 462 463 464 465 466 467 468 469 470 471 472 473 474 475 476 477 478 479 480 481 482 483 484 485 486 487 488 489 490 491 492 493 494 495 496 497 498 499 500 501 502 503 504 505 506 507 508 509 510 511 512 513 514 515 516 517 518 519 520 521 522 523	
--	--

FIGURE 8

APPENDIX G
REGIONAL VICINITY MAP

